# Oil Field Environmental Incident Summary

Incident: 20150723233802 **Date/Time of Notice:** 07/23/2015 23:38 Responsible Party: SLAWSON EXPLORATION COMPANY, INC. SLAWSON EXPLORATION COMPANY, INC. Well Name: MAUSER (FEDERAL) 7-18-17H Field Name: NORTH FORK Well File #: 25433 Date Incident: 7/23/2015 Time Incident: 06:15 Facility ID Number: **MCKENZIE Sec:** 18 **Qtr:** County: **Twp:** 153 **Rna**: 97 **Location Description:** Submitted By: Raymond Gorka Received By: Ray Gorka Contact Person: **1675 BROADWAY STE 1600** DENVER, CO 80202 General Land Use: Pasture Affected Medium: Well/Facility Soil 3000 Feet Distance Nearest Occupied Building: 3000 Feet Distance Nearest Water Well: Type of Incident: Tank Overflow Release Contained in Dike: Yes - Within Dike Reported to NRC: No Units Spilled Recovered Units **Followup Units** Oil **Brine** 20 **Barrels** 19 **Barrels** 20 barrels Other Description of Other Released Contaminant: Inspected: Written Report Received: 4/18/2016 Clean Up Concluded: 7/23/2015 Risk Evaluation: ..... Areal Extent:

......

### Potential Environmental Impacts:

minimal, to none, water contained within dike, which has a layer of bentonite under it.

### Action Taken or Planned:

Steel berm contained spill. Vacuum truck and wash crew arrived to cleanout spill.

Wastes Disposal Location: Disposal well for final disposal.

Agencies Involved:

## **Updates**

Date: 7/24/2015 Status: Reviewed - Assigned to Other Agency Author: Crowdus, Kory

**Updated Oil Volume:** 

**Updated Salt Water Volume:** 

**Updated Other Volume:** 

**Updated Other Contaminant** 

### Notes:

Release, due to a tank overflow, remained on location according to the report. NDIC retains oversight.